




Motor
 is 12V
 wound field
 Full load amp 3.3
 Rpm 2500 no load

Each Coil
 is 100 Turns
 of 14 gauge
 Magnet wire